



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

#### Inspection Report

#### Minerals Regulatory Program

January 19, 2007

Supervisor DRH

**Mine Name:** North Shore Natural Processing  
**Operator Name:** Northshore Limited Partners

**Permit number:** M0030037  
**Inspection Date:** June 14, 2006  
**Time:** 2:30 pm

**Inspector(s):** Lynn Kunzler, DOGM  
**Other Participants:** Lee Medford  
**Mine Status:** Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

This was a routine inspection while in the area.

#### Inspection Summary:

This site was active (considering it is a evaporation operation). Evaporation ponds were near the full level. All the permitted disturbance (with the exception of the office trailer and pump station) were fenced to keep public out of the ponds. There has been no new ponds constructed since the last inspection.

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

This site is in compliance at this time. Continue to monitor this site when in the area.

**Inspector's Signature** [Signature]

LK:pb

**Date:** January 19, 2007

O:\M003-BoxElder\M0030037-NorthshoreLimited\inspections\Insp-06142006.doc